



POSITION GUIDELINE

POSITION: Fabricator Class II

DEPARTMENT: Production

REPORTS TO: Fabricator Lead Hand

DATE PREPARED: Feb 3, 2009

BRIEF DESCRIPTION OF RESPONSIBILITIES

- Responsible for working safely in accordance with JNE procedures and OH&S regulations. This includes wearing appropriate personal protective equipment, using appropriate equipment and rigging, and maintaining good housekeeping in job area.
- Interpret drawings and organize work space and equipment.
- Determine schedule requirements and perform work efficiently to meet schedule and estimates.
- Assembling, fitting and welding of a fabrication according to specifications and drawings. By verifying the wire, gas, settings and the weld prep against the weld procedure for each weld.
- Material handling and moving of finished product.
- Responsible and reasonable control of raw material inventory.
- Participate in developing more efficient methods, procedures, and training of less experienced employees. This includes giving direction in welding techniques in different processes.
- Work on fitting simple fabrications. And to start to learn the fitting techniques of the more complicated fabrications.

We will provide the resources and the framework for our employees to do whatever it takes to get the job done. Each employee is expected to act within the scope of this guideline but also be flexible in the performance of his or her duties in the JNE environment.

DESIRED QUALIFICATIONS

- 5 to 7 years related experience
- Good layout, organizing and fabricating skills
- Pre-employment welding or fabrication.
- Grade 10 with math

DESIRED WELDING PROCESS QUALIFICATIONS

- ASME Section IX – FCAW 1G Roll.
- CWB W47.1 – MCAW / FCAW O.

EMPLOYEE ACKNOWLEDGEMENT:

DATE:

APPROVED BY:

DATE:

